Refer to the Summary document for more elaboration on replacement and maintenance plan

Truckee Talloe All	POILIVI	annice	Hance I I	all- Wieci	ilailica	a1		Assumed		Refer to the Su	immary docui	nent for mo	re elaborati	on on repia	cement and n	naintenance p	olan		1												
Picture	Unit type	Quantit	Manufacturer	Model	Fuel type	Innut	Output	Assumed Original Efficiency	Size	Manufactured	Bracing	Flue/ Duct	Controls	Starts and	Other	Replace	Replacement	Maintenance	Maintenance Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	0023-2027	2028-2032
Maintenance Building	Offic type	У	ividilulacturei	iviodei	i dei type	Imput	Output	Littleficy	Size	ivianulactureu	bracing	riue/ Duci	Controls	Ruis	Other	Nepiace	COSC	ividiliteridilice	COST	2013	2014	2013	2010	2017	2018	2019	2020	2021	2022	.023-2027	2028-2032
	Water Heate	r 1	Bradford White	MI50456LN10	Natural Gas	50,000 BTU		80%	50 Gallons	1997	yes although wall screws may not be sufficient	seems	Auto/ Water temp		Drain pan, PTRV, no Insulating blanket	2017	\$ 1,000	2013 Replace Wall Screws with Lag Screws, Add thermal Blanket		100				1000							
	Furnace	1	Carrier	58RAV095-12	Natural Gas	92,000 BTU	74,000 BTU	80%		1997	Duct is hung not braced although thi probably is sufficient	tight, Needs	Honeywel I Program mable Thermost at	Yes	Filter needs to be changed, duct work should be cleaned Both outside air vents need to be open	2017 With a 92% efficient furnace and adda condensate drain line, reconfigure flues and new programma ble thermostat	\$ 6,000	Twice yearly Change Filter	\$ 50	50	50	50	50	6000	50	50	50	50	50	250	250
	Radiant Heaters	10	Modine	MHR 30 or 60	Natural Gas	30,000 or 60,000				1997?	yes	None	3 generic thermosta ts	yes, except for mezzanin e which appears to have the circuits switched off.	Unit in North Bay has burnt/melte d plastic on grill. Insure that batting net is uncompromi sed	failure replaceme nt a year starting in	\$1000/ year					1000	1000	1000	1000	1000	1000	1000	1000	2000	
	Ceiling Fans	5	Unknown	Unknown 52" Diameter approximately	Electric					2004?	None	none	Dial fan speed	Yes		2020 replace all 5 fans and controls	\$2,000	Add Humidistat control and on/off/auto switch	\$500	500							2000				
	Bathroom Exhaust Fans	2	Penn Zephyr	Unknown	Electric				unknown- larger capacity	1997?	None	seems tight	Occupanc y Sensor	Yes		2017	\$800							800							
	South Bay Exhaust Fan	1	Power Ventilator Co.	SX105BC	Electric						yes		Time Dial	Yes				Install CO and combustible gas sensor for auto turn on & Lubricate	\$1000 Initial and \$50 year	1050	50	50	50	50	50	50	50	50	50	250	250

7/15/2013 10f13

Truckee Taho	Airnort N	/laintenance	Plan-	Mechanical

Refer to the Summary document for more elaboration on replacement and maintenance plan

Truckee Tahoe Air	port ivi	ainte	nance Pi	an- iviec	nanica	11		Tanana and		Refer to the Su	mmary docur	nent for mo	re elaboration on re	lacement and n	naintenance p	lan														
D. J.	Unit type	Quantit	Manufacturer					Assumed Original Efficiency	57	Manufactured		51 - 15 - 11	Starts as	d Other		Replacement	Maintenance	Maintenance	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2022 2027	2028-2032
Picture	Vehicle Exhaust Fans		DSP-Monoxiven		Fuel type	input	Output	Efficiency	Size	1997?	Bracing	Flue/ Duct	Yes	Other	2037	cost	Might need to replace electrical contactors every 5 years depending on use	200	200	2014	2015	2016	2017	200	2019	2020	2021	2022	200	200
	Fire Suppression	1		Wet													Annual Inspection, Occasional Head failure or leak fixing	\$100 yearly for heads in addition to inspection	100	100	100	100	100	100	100	100	100	100	500	500
	Grease interceptor	1	Unknown														Routine cleaning	assumed already included in budget												
Recommended	CO and combustible gas alarm for North Bay														2013	\$1,000			1000											
Recommended	Insulation																Fix loose insulation in north bay	\$ 300.00	300											
Warehouse A																														
	Unit Heaters	2	Reznor		Natural gas					1994?	No lateral bracing		Did no attemp boxes tr Basic close, thermosta t been started at least years	10 years life remaining if used		\$ 4,500	Add lateral brace ASAP 1.5ft clearances must be maintained	\$ 800	800										4500	

7/15/2013 20f13

	Truckee Ta	hoe Airport	Maintenance P	lan- Mec	hanical
--	------------	-------------	---------------	----------	---------

Refer to the Summary document for more elaboration on replacement and maintenance plan

Truckee Tahoe Air	port ivia	mter	lance Pi	an- iviec	Hallica	11				Refer to the Su	mmary docur	nent for mo	re elaborati	on on repla	cement and m	aintenance p	lan		1												
Picture	Unit type	Quantit v	Manufacturer	Model	Fuel type	Input	Output	Assumed Original Efficiency	Size	Manufactured	Bracing	Flue/ Duct	Controls	Starts and Runs	Other	Replace	Replacement	Maintenance	Maintenance Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022 2	023-2027 2	028-2032
The !	Exhaust fan	1									None				Not currently used			If going to be used need new belts & lube.													
Warehouse B	Unit Heater	2	Reznor	UDAP175	Natural Gas	175,000 BTU	145250 BTU	83%		Sep-02	No lateral bracing	Could use sealing	Basic thermosta t	yes	Dusty fan needs cleaning	2022 93% efficiency Reznor UEAS-130	\$ 9,000	Add lateral brace ASAP Add programmable thermostat	\$800 & \$600	1400									9000		
Warehouse C	Unit Heaters	2	Reznor	FE 165-H	Natural gas	165,000 BTU	132,000 BTU	80%		1994	No lateral bracing	Seems tight	Basic thermosta t	Did not attempt, boxes too close		2024 with 93% efficiency UEAS-130 if used	9000	2013 Add lateral brace	\$ 800	800										9000	
Warehouse D	Unit Heater- non operating?	1	Reznor	FE 165-H	Natural gas	165,000 BTU	132,000 BTU	80%		1994?	No lateral bracing	Seems tight	Basic thermosta t	Did not attempt, Trailer too close				2013 Fill in wall and fire caulk at flues to provide 1 Hour fire rating Change flue to double wall or move termination to within space Add Lateral Bracing	\$900	900											
	Unit Heater operating	1	Reznor	FE 165-H	Natural gas	165,000 BTU	132,000 BTU	80%		1994?	No lateral bracing	Seems tight	Program mable thermosta t	Running	Fans wired up in front of unit	2014 with UEAS-180 & add lateral bracing	6000	2013 remove fans Fill in wall and fire caulk at flues to provide 1 Hour fire rating	\$ 1,500	7500											
Warehouse E2	Unit Heater	1	Reznor	FE 165-H	Natural gas	165,000 BTU	132,000 BTU	80%		1994?	No lateral bracing	Seems tight		Did not attempt, too much paper	Space needs special consideratio n given the amount of paper files here	2024 with 93% efficiency UEAS-130 if used	4500	2013 Add Lateral Bracing	400	400										4500	
Recommended															Additional fire/smoke separation because of large amount of paper	2013 Confirm fire ratings	4000			4000											

7/15/2013 3of 13

Refer to the Summary document for more elaboration on replacement and maintenance plan

Truckee Tarloe All	po. c	Quantit	Tiurice i i	14166	Ilainee	··		Assumed Original		Kerer to the Su	Illinai y docum	lent for mo		arts and	inent and in		Replacement		Maintenance												
Picture	Unit type	у	Manufacturer	Model	Fuel type	Input	Output	Efficiency	Size	Manufactured	Bracing	Flue/ Duct	Controls Ru		ther			Maintenance	Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022 2	023-2027 2	028-2032
Warehouse E3	Unit Heater	1	Reznor	FE 165-H	Natural gas	165,000 BTU	132,000 BTU	80%		1994	No lateral bracing		Basic thermosta t	yes s	May require fire/smoke eparation & explosion-	2013 Confirm fire ratings 2017 Add programma ble thermostat	TBD	2013 Add Lateral Bracing	400	400											
	Exhaust Fan	1											could not find			Not in use. If used need to lubricate and change belts															
Warehouse Bathroom																															
	Wall Heater	1	Unknown	Unknown	Electric	Unknown	Unknown			1970's?	None	None	dial	yes sa	No guard, afety hazard	2013 with Electric Hydronic wall heater	\$200			200											
	Water Heate	r 1	Hoyt	6 FC	Electric	1500 Watts			6 Gallons	1980's?	None	N/A		yes		2014 add lateral bracing	\$600				600										
	Exhaust Fan	1	Unknown											yes		2025	\$300													300	
	Portable radiant Heate	er 1													remove when properly sized wall heater is installed																

7/15/2013 4of 13

Refer to the Summary document for more elaboration on replacement and maintenance plan

Truckee range Air	port iv	unite	nance i i	all wice	Harrice	<i>a</i> 1		Assumed		Refer to the su	IIIIIIary docui	nent for mo	re elaboration on i	piacement and	maintenance	pian		1												
		Quantit						Original					Starts			Replacement		Maintenance												.
Picture	Unit type	У	Manufacturer	Model	Fuel type	Input	Output	Efficiency	Size	Manufactured	Bracing	Flue/ Duct	Controls Runs	Other	Replace	cost	Maintenance	Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023-2027	2028-2032
Hanger M	Dry Fire Suppression	1													2025 replace air compressor		Replace heads as needed	\$100/year	100	100	100	100	100	100	100	100	100	100	1500	500
	Unit Heate	r 1	Reznor	EGE02	Electric										2025	\$750													750	
	Water Heati	er		Unknown	electric				10 gallon?						2025	\$500													500	
	Exhaust Fai	1													2025	\$200													200	
Hanger L	Unit Heate	r 1	Reznor	EGE02	Electric										2025	\$750													750	
	Dry Fire Suppression	1													2025 replace air compressor		Replace heads as needed	\$100/year	100	100	100	100	100	100	100	100	100	100	1500	500
Careflight	Cooktop Exhaust Fai	1								2011	None				2032	\$400	Inspect quarterly & clean filters as needed													400

7/15/2013 5of 13

Refer to the Summary document for more elaboration on replacement and maintenance plan

Truckee Tanoe Air	port ivid	annice	ilalice Fi	all- Wieci	iaiiica	11				Refer to the Su	immary docur	nent for mo	re elaboratio	n on replac	cement and m	naintenance p	lan														
Picture	Unit type	Quantit	Manufacturer	Model	Fuel type	Input		Assumed Original Efficiency	Size	Manufactured	Bracing	Flue/ Duct	Controls F	Starts and Runs	Other		Replacement	Maintenance	Maintenance Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	023-2027	2028-2032
	Water Heater	. 1	Bradford White	M440T6FBN	Natural Gas	40,000 BTU		80%	40	October 2011	Yes	Common with Furnace		yes		2032	\$1,000	Brace Flue ASAP	\$200	200											1000
LENNOX medicine to the control of th	Furnace	1	Lennox	G16Q4-75-1	Natural Gas	75,000 BTU		79.10%		1985	Flue needs more bracing	Common with Water Heater	Program mable Thermost at		Air filter needs to be changed	2015	\$4,000	See above for Flue change air filter twice yearly	60	60	60	4060	60	60	60	60	60	60	60	300	300
	Air conditioning	1	Carrier	38CKC036340	Electric	208V/ 30A Rating			3 Ton	2000						2015	\$2,000	Refrigerant recharge if needed	\$200	200		2000									
	Bath Exhaust Fan	2	Unknown		Electric								wall switch			2025	\$400													400	
Garage	Unit Heater	1	Reznor	FE200-H	Natural gas	200,000 BTU	160,000 BTU	80%		1994	No lateral bracing	Needs to be sealed		Yes	Needs to be dusted	2024 with 93% efficiency UEAS-130 if used	4500	Add lateral brace ASAP	400	400										4500	

7/15/2013 60f13

Refer to the Summary document for more elaboration on replacement and maintenance plan

Truckee rande An	p 0 . c	11111111	iance i i	111100	Harrice	1		Assumed	1	Neier to the 30	Illinary docum	lent for mo	re elaboration (onrepiac	ement and m	amtenance p	idii	1	1		-	-				1	- 1		- 1	-	
Picture	Unit type	Quantit	Manufacturer	Model	Fuel type	Input	Output	Original Efficiency	Size	Manufactured	Bracing	Flue/ Duct	Sta Controls Rui	arts and	Other		Replacement cost	Maintenance	Maintenance Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	1023-2027	2028-2032
	Water Heater		Rheem	81VP108	Electric	2000 Watts			10	1992	None	None		Yes		2017	\$500	Add Lateral bracing	50	50				500							
	Bath Exhaust Fan	1	Unknown		Electric								Wall Switch			2020	\$200										200				
	Abandoned Wall heater	1											Basic thermosta t	No				Make sure circuit is disconnected	\$100	100											
EAA	Exhaust Fan	1	Acme Centri Master	PNU135RGG2	Electric		1/2 HP						Switch		No Fire Suppression exists under hood	2013 Move fan to roof to provide code clearances Add Fire Suppressio n to hood	\$5,000	Clean, Change Belt,	\$ 50	5050	50	50	50	50	50	50	50	50	50	250	250
	Furnace	1	Rheem	RGRA-10EZAIS	Natural Gas	105,000 BTU	97,000 BTU	92%		2000					2025	\$6,000		Add additional strapping including lateral bracing to duct. Change filter twice yearly. Condensate drain exits side of building and drips onto walkway which is not best practice should go to sewer drain. Add condensate neutralizer. Add 1/4" screen to flues for code pest control	200 , 60, & 300	560	60	60	60	60	60	60	60	60	60	6300	300

7/15/2013 70f13

Refer to the Summary document for more elaboration on replacement and maintenance plan

Truckee Talloe All	ρυιτιν	iaiiite	illalice Fi	all- Wiec	Harrice	71				Refer to the Su	mmary docun	nent for mo	re elaborati	on on repla	cement and n	naintenance p	olan														
		Quanti	t					Assumed Original						Starts and			Replacement		Maintenance												.
Picture	Unit type Water Heat	у	Manufacturer Noritz	Model N-063S	Fuel type Natural Gas		Output	Efficiency	Size	Manufactured 2004	Bracing	Appears acceptabl	Controls	Runs	Other		sz,000	Maintenance	Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023-2027	2028-2032
	Domestic Range Hoo												Switch	No	Assumed not used																
	Wall Furnar	ee 1	Louisville Tin & Stove Co.	DVC 5 92	Natural Gas	55,000 BTU		75-80%		1994?			Basic Thermost at	No	Spark ignition but gas did not turn on	2013 By extending duct from furnace and removing this unit	\$500			500											
	Bath Exhau Fan	st 2	Unknown													2020	\$200										200				
	Exhaust hor and Fan	od 1	Coleman adapted furnace										Switch	yes	Backdraft damper is not automatic																
Garage space- Unable to access	Furnace Likely same other EAA furnace	as 1								2000?					2025	\$6,000		Add additional strapping including lateral bracing to duct. Change filter twice yearly. Condensate drain exits side of building and drips onto walkway which is not best practice should go to sewer drain. Add condensate neutralizer.	200 , 60, & 300	560	60	60	60	60	60	60	60	60	60	300	300

7/15/2013 8of 13

Refer to the Summary document for more elaboration on replacement and maintenance plan

Truckee Tanoe All	POI L IVI	annic	Hance Fi	all- Wiec	Harrica	11				Refer to the Su	ımmary docun	nent for mo	re elaboration on repla	cement and m	naintenance p	lan													
Picture	Unit type	Quantit	Manufacturer	Model	Fuel type	Input	Output	Assumed Original Efficiency	Size	Manufactured	Bracing	Flue/ Duct	Starts and Controls Runs			Replacement cost		Maintenance Cost	2013	2014	2015	2016 20	17 201	8 201	2020	2021	2022	2023-2027	2028-2032
Hanger 1	Unit Heater	s 3	Reznor	FE250	Natural Gas	250,000 BTU	200,000 BTU	80%		1994	No Lateral Bracing	Might need sealing	Basic Thermost at		2018 with UEAS-260 & adjust lateral bracing	18000	Add lateral brace ASAP	1500	1500				18000						
	Unit Heater	1	Reznor	UDAS200	Natural Gas	200,000	166,000 BTU	83%		2010	Lateral Bracing				2035 with UEAS-260	\$6,000													
	Water Heate	r 1	GE	GESOTO6AAG	Electric	4500 Watts			50 Gal	2006	No Bracing	N/A	Yes		2031 with Natural gas fired unit	\$1,500	Add lateral bracing ASAP	50	50										1500
	Furnace	1	BDP/Carrier	395CAV060133	Natural Gas	132000 BTU	107,000 BTU	81%		1994			lock box over bottom thermosta ts? ts? ts? ts does not work		2018 with 92% Efficient model with AC	\$8,000	Change Filter	\$60 yearly	60 ε	0	60	60 60	8060	60	60	60			
	Bath Exhaus Fan	t 2	Unknown												2014	\$400			40	00									
2 6	Shower	1	Unknown														replace valve set	\$ 400	400										

7/15/2013 90f13

Truckee Tahoe Air	rport M	ainte	nance Pl	an- Mec	hanica	al				Refer to the Su	mmary docur	nent for mo	ore elaborat	on on repla	cement and n	naintenance p	lan														
District	Unit type	Quantit	Manufacturer	Madel	Front home	lant	Outmut	Assumed Original Efficiency	Cina	Manufactured	Dessins	Flore / Done	Cantrola	Starts and	Other	Danlass	Replacement	Maintanana	Maintenance Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023-2027	2020 2022
Picture	Spray insulation	У	Manufacturer	Model	Fuel type	input	Output	Efficiency	Size	Manufactured	Bracing	Flue/ Duct	t Controls	Kuns	Other	When used regularly 2014?	\$20,000	Maintenance 2013 Seal holes to outside		500	20,000	2015	2016	2017	2018	2019	2020	2021	2022	2023-2027	028-2032
Recommended Hanger 2																															
Hanger 2	Unit Heater	1	Reznor	SCA250-6	Natural Gas	250,000 BTU	200,000 BTU	80%		1990's?		Combusti on & Exhaust	Thermost	Yes		2015 with UEAS-180 & adjust lateral bracing	6000	Add Lateral bracing ASAP	400	400		6000									
	Furnace	1	Rheem	RGAA-125A	Natural Gas	125,000 BTU	100,000 BTU	80%		1979?			Basic Thermost at			2013 Replace with 92% condensing furnace and programma ble thermostat	\$ 5,000.00	Replace filter twice yearly	60	5060	60	60	60	60	60	60	60	60	60	300	300
	Bath Exhaus Fans	t 2	Unknown													2013	\$400			400											
	Water Heate	er 1	GE	GE30506AAG	Electric	4500 Watts			30 Gal	2012	No Lateral bracing	N/A		Yes		2037	\$600	Add lateral brace ASAP	s 50	50											
	Wall Furnac	e 1	Williams	450FX-R	Natural Gas	50,000 BTU	37,500 BTU	75%		1986?		yes	Program mable Thermost at	yes		2013 Duct from furnace below and remove unit	1000			1000											

7/15/2013 10of 13

Truckee Tahoe	Airport Maintenanc	e Plan- Mechanica	ıl

Truckee Tahoe Air	port Ma	ainte	tenance Plan- Mechanical Refer to the Summary document for more elaboration on replacement and maintenance plan Assumed Original Starts and Replacement Maintenance Maintenance Plan																										
Picture	Unit type	Quantit	Manufacturer	Model	Fuel type	Input	Output	Original	Size	Manufactured	I Bracing	Flue/ Duct Controls	Starts and	Other	Replace	Replacement	Maintenance	Maintenance Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023-2027 2028-2032
Modular Bard	Wall Furnace, AC		Bard	WA242- A10xx4xxx	Electric	14,000 Watts				2000?		Thermos			2016	\$2,000						2000							
Heriz	Furnace	1	Bryant	376CAV	Natural Gas	69,000 BTU	56,000 BTU	81%		1997			Yes		2022 Replace with 92% condensing furnace and programma ble thermostat and air conditionin	\$ 8,000.0	Add lateral bracing to ducts	200	200									8000	
	Water heater	. 1	Bradford White	MII30R6DS13	Electric				44 Gal						2030	1500	Remove Insulating blanket, not needed and add lateral bracing, Insulate pipes	\$200	200										1500
	Wall Heater	2	Unknown									dial	No		Remove and disconnect circuit	100			100										
Civil Air Patrol	Electric Wall Heater	2	Various		Electric								yes	Downstairs	2013 with electric hydronic wall heater	800			800										
	Portable Electric Heate	r ²												Fire Hazard	2013 with electric hydronic wall heater	\$800			800										

7/15/2013

Refer to the Summary document for more elaboration on replacement and maintenance plan


Picture	Unit type	Quantit y	Manufacturer	Model	Fuel type	Input	Assumed Original Efficiency	Size	Manufactured	Bracing	Flue/ Duc	t Control:	Starts and		Replacement cost		Maintenance Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022 2023-2027 2028-2032
	Unused ducts and fans	3														Remove and close up	200	200									

7/15/2013 12of 13

Refer to the Summary document for more elaboration on replacement and maintenance plan

		Quantit					Assumed Original					Starts an	d	Repla	lacement		Maintenance												
Picture	Unit type	/ Manuf	cturer Mo	odel	uel type Input	Output	Efficiency	Size	Manufactured	Bracing	Flue/ Duct Controls	Runs	Other Repla	e cost	t	Maintenance	Cost	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023-2027 20	J28-2032
Airport Wide																													
	Plumbing fixtures (toilets/sinks etc.)												Pla repl o fixtu	cing e \$5	5500 yearly		\$500 yearly	500	500	500	500	500	500	500	500	500	500	2500	2500
	Natural gas lateral bracing												Various locations are not well secured			Add bracing & Strapping	\$1,000	1000											
Total		84															Grand Total	40,800	22,250	14,250	4,250	10,500	28,450	2,250	4,650	2,250	19,190	41,550	12,550 202,940

7/15/2013



Truckee Tahoe Airport District Maintenance Plan Summary of Mechanical Observations and Recommendations July 15, 2013

observed are for space heating & cooling, water heating, ventilation and exhaust. The units ranged in age from more included in this report because of their recent installation and predicted life is greater than 20 years. The units that were than 35 years old to 4 months old. 84 individual mechanical units were observed and cataloged. The units at the new Administration Building are not As requested PBD, Inc. has conducted a thorough investigation of the Mechanical systems at the Truckee Tahoe Airport.

timeframes are given. Costs are listed per year for the first 10 years, then every 5 years for years 11-20. Costs are given The attached spreadsheet details each unit sorted by building. Recommended maintenance and replacement costs and in 2013 dollars. This report does not intend for forecast inflation or construction cost escalation.

and is providing adequate heating, ventilation or air conditioning. Licensed engineers and contractors should be used to The recommendations do not include system design. We have assumed that the existing equipment is adequately sized at the time of unit replacement. registered Mechanical Engineer is recommended to optimize energy efficiency and comfort, based on actual facility use confirm suitability and size, and install proposed equipment per codes and industry standards. Retaining a California

Items listed for 2013 should be addressed as soon as possible because of code deficiencies, hazards, or likely early

in the Warehouse areas, Maintenance Garage and Hangar 1 see limited use and will probably last for 5-10 years or be impractical or cost prohibitive, in which case 82% models can be used. replaced with 92% efficient models. However, these models require a condensate drain plumbed to sewer, which may New bracing on an old unit would later need to be adapted if the unit is replaced. now with proper bracing. On units that will see less use and are not critical, seismic bracing should be installed now. more. However they are not seismically braced and are unsafe. In high-use areas we recommend replacing the units There are a few systems that will require more decision making based on their expected use. For example, most heaters Ideally the unit heaters should be

elevated costs and temporary heating) can be avoided. Some units may last longer than expected. We recommend the The recommendations assume it is better to plan for replacement of the units so unexpected failure (with associated District evaluate their risk tolerance with respect to sudden failure of a unit.

tested annually. We recommend at a minimum, every piece of equipment be annually inspected by a qualified every routine maintenance activity. For example, all water heater temperature and pressure relief valves should be In addition to the listed maintenance, other routine maintenance is required. This report does attempt to describe

notification may put occupants at risk. District should review with their attorney prior to any notifications On leased spaces, we recommend the following notifications be sent to tenants in some fashion. Avoiding this

- <u>-</u> equipment. Changes may be required to the equipment to bring it into compliance. Tenant has installed equipment and is responsible for code compliance, maintenance, or repair of that
- 2 other changes. Tenant may be using the space in a manner that requires construction of fire-ratings, equipment upgrades, or

So the District can prepare, the units will likely fail or loose efficiency in the following manner:

the unit. Heat exchanger perforation can result in carbon monoxide poisoning. and result in a repair that is almost as costly as a complete replacement. At this point it is better to completely replace Unit Heaters: Although many smaller parts may fail incrementally, eventually the heat exchanger will become corroded

Furnaces: Although many smaller parts may fail incrementally, eventually the heat exchanger will become corroded and result in a repair that is almost as costly as a complete replacement. At this point it is better to completely replace the Heat exchanger perforation can result in carbon monoxide poisoning.

especially for the smaller types. Gas burners, solenoid valves, and similar devices can be replaced. Tank leakage should Water Heaters: Electric water heaters will usually fail by corrosion of the heating element. The heating elements can be result in replacement. Many water heaters do not have pans under them, so visual inspection is imperative replaced if a compatible element can be located. It may be faster and more cost effective to replace the entire unit,

Exhaust Fans: Bearings will usually fail in exhaust fans. Belts may also break in indirectly driven fans. Belts are not too much. Belt and bearing failure may cause audible noise. catastrophic but bearings can be. They will lose efficiency over time but will usually fail before efficiency is compromised

building is more understood. \$3,000 per year for the next 3 years should be budgeted for this optimization. It is also recommended that the administration building mechanical systems be further optimized as the use of the

an exhaustive report. Please note that this report is based on visual observation, engineering judgment and experience. No destructive testing or destructive investigation was performed This is not

desired. PBD, Inc. Capabilities include thermal imaging, airflow measuring, and further physical investigations. is available to perform additional, detailed reviews if confirmation of any of the above

Respectfully submitted

Peter Beaupre, P.E.