

Runway 02 Departure

- Runway 02 is the preferred departure for noise and offers the most options in the event of a loss of power.
- For a successful departure please fly runway heading until **abeam** Sewage Treatment plant, then left to Truck Scales . Turning before Sewage Treatment plant results in overflight of homes. Flying straight out to the freeway will also result in overflight of homes.
- If departing Runway 11, after gaining altitude, follow Runway 02 departure procedure.

