

Runway 02 Departure

- Runway 02 is the preferred departure for noise and offers the most options in the event of a loss of power.
- For a successful departure please fly runway heading until **abeam** Sewage Treatment plant, then left to Truck Scales. Turning before Sewage Treatment plant results in overflight of homes. Flying straight out to the freeway will also result in overflight of homes.
- If departing Runway 11, after gaining altitude, follow Runway 02 departure procedure.

